



PICTURE 1 – SIDING IN DISREPAIR



PICTURE 2 – MISSING SKIRTING



PICTURE 3 – SIDING IN DISREPAIR



PICTURE 4 – DAMAGE TO DOORWAYS



PICTURE 5 – SIGNIFICANT WEAR ON STRUCTURAL FRAME



PICTURE 6 – LIGHTING SEPARATED FROM JUNCTION BOX



PICTURE 7 – HOLES IN SUBFLOOR, REMNANTS OF INFESTATION



PICTURE 8 – STANDING WATER ON ROOF



PICTURE 9 – PLUMBING OUT OF SERVICE



PICTURE 10 – SIGNS OF WATER DAMAGE IN CEILING



PICTURE 11 – INADEQUATE SECURITY MEASURES



PICTURE 12 – ADDITIONAL OPERATIONAL COSTS TO SUPPORT HEATED PORT-A-POTTY