

Attachment 1: Options to Address Vandalism at Kapasiwin Transfer Station

| Option | Description | Cost | Advantage | Disadvantage | Risk |
|--------|--|-------------|---|---|---|
| 1 | No Longer Receive Metals and Electronics at the Kapasiwin Transfer Station | Negligible. | Greater probability of successfully eliminating the incentive for vandalism. | Customers having to drive further distance to another transfer station to discard metals and electronics. | Probability that acts of vandalism would migrate into the Amisk Acres Sub-division. |
| 2 | Reduce Metals and Electronics Stock Pile at the Kapasiwin Transfer Station | \$28,000 | Customers can continue to bring metals and electronics to the Kapasiwin Transfer Station. | Increased operational costs resulting from increased frequency of Contract pick-up. Metals and electronics still on site, in smaller amounts. | Lower probability of success in reducing vandalism at the Kapasiwin Transfer Station. |

Other Actions to Address Vandalism at Kapasiwin Transfer Station

| Description | Advantage | Disadvantage | Risk |
|---|--|---|--|
| Engaged RCMP and Enforcement Services to increase presence. | Will be a strong deterrent to vandalism | RCMP and Parkland County Enforcement Services do not have resources to increase site monitoring to a level that will influence vandalism. | |
| Retain after-hours site security. | Will be a strong deterrent to vandalism | Cost prohibitive | Previously attempted random after-hours surveillance was not effective. |
| Site Modifications. Installed video surveillance at trail entrances. Upgraded Locks at front entrance. | Demonstrated increased surveillance and vandal proof locks may be a deterrent for vandalism. | Vandals disguise their appearance, causing captured information to not be of use. | Vandalism may not reduce if no action results from video surveillance. Vandals gain site access through other perimeter locations. |
| Site modifications. Make site more visible by removing front foliage to allow visibility from Township Road 533A. | Increased visibility may be a deterrent for vandalism | Regular site operations are visible to members of the community, passing on the road. | Vandalism may not reduce, if response time is delayed. |
| Remove all site contents from site at the end of every operational day. | Will be a strong deterrent to vandalism | Cost prohibitive. Resources not available. | |